

## **UNI-TREND UT207B**



LCD clamp meter - DC measurement up to 1000V and 1000A - Measurement in AC up to 1000V and 1000A - Resistance/capacitance/frequency - Auto Range | Test diodes| True RMS | NVC - Clamp opening of 42mm

- UNI-T
- Clamp meter CAT III 1000V/ CAT IV 600V
- LCD display up to 6000 accounts
- DC and AC current measurement up to 1000 A
- DC and AC voltage measurement up to 1000 V
- High accuracy in AC with built-in True RMS function
- Resistance and capacitance measurement
- Buzzer for continuity test
- Diode test
- NCV (non-contact voltage) function
- Low pass filter
- Automatic shutdown